

Repair instruction

Description: SC400 Holdingtank mechanism R/L

Part number: 3233106/3233206

Look for Service Centres, Point of Sale addresses and other information on: www.thetford-europe.com

Version:

1

Date:

April 2010

Tools required:

-

A

Using the sliding cover as a lever rotate the complete mechanism anti clockwise until the arrow points to the second dot



B

Take complete mechanism out and replace it by the new one.



C

Place new mechanism and use sliding cover in reverse to position back into the tank.



Note: a new sliding cover is not included in the package.